

---

## BELZONA® 1111 SUPER METAL SAVES COUCH ROLL

---

### CUSTOMER

PULP AND PAPER  
Campbell River, BC.

### APPLICATION DATE

August 2000

### PROBLEM

A foreign object had badly damaged the inside of the couch roll.

### PRODUCTS

Belzona® 1111 Super Metal

### SUBSTRATE

Bronze

### APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet GSS-8

### BELZONA FACTS

The use of the Belzona® repair procedure enabled the mill to repair the damaged area of the couch roll on site in less than 2 days. The alternative would have required shipping the roll to Vancouver incurring tens of thousands of dollars in extra costs for shipping, welding and machining.

### PHOTOGRAPHS

1. View of damaged couch roll with repair area masked off ready for rebuildin
2. Damaged area rebuilt and plastic forms wedged in place in preparation for drilling.
3. Holes being re-drilled from the outside.
4. View of partially completed area.

