
BELZONA® REBUILDS OVERSIZE PIN BUSH HOUSING

CUSTOMER

Mining Group
Tumbler Ridge, BC.

APPLICATION DATE

1994

PROBLEM

The bush housing had worn oversize

PRODUCTS

Belzona® 1111 Super Metal

SUBSTRATE

Steel

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet MPT-7

BELZONA FACTS

Repair could be done onsite with the minimum amount of downtime

PHOTOGRAPHS

1. Oversize Housing.
2. Outer race used as a former
3. Trial fit
4. Completed application.

