

## EMERGENCY REPAIR USING BELZONA®2311 - SR ELASTOMER

### CUSTOMER

Mining operation

### APPLICATION DATE

September 2005

### PROBLEM

A large hole had formed in this conveyor belt stopping production

### PRODUCTS

Belzona® 2311 SR Elastomer

### SUBSTRATE

Reinforced rubber conveyor belt

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet SHM-1

### BELZONA FACTS

The use of Belzona® 2311SR Elastomer enabled maintenance to make the necessary repairs with the minimum amount of downtime and loss of production.

### PHOTOGRAPHS

1. View of damaged conveyor belt showing the product used to make the repair.
2. Close up of repair area showing the use of the Belzona mixing surface positioned on the underside to act a suitable temporary backing for the repair.
3. Completed application

